HONDA

Service Bulletin

November 18, 2020

Version 2

Service Manual Update: CR-V and CR-V Hybrid Alignment Specification

Supersedes 20-048, dated June 23, 2020, to revise the information highlighted in yellow.

AFFECTED VEHICLES

Year	Model	Trim Level	VIN Range
2017 <mark>–21</mark>	CR-V	ALL	ALL
2020 <mark>–21</mark>	CR-V Hybrid	ALL	ALL

REVISON SUMMARY

2021 models were added.

BACKGROUND

The rear total toe-in specification has changed.

Current	3.5 ⁺¹ -2 mm
Updated	2.4 ± 0.9 mm

NOTE

The database in your alignment equipment may not currently reflect this change.

END

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.