



December 14, 2020

RE: PCM Code Changes Jan 1, 2021

Effective January 1st 2021, PCM Codes will be increased from 4-digits to 16-digits in length. This is a requirement to adhere to increased cybersecurity measures by American Honda.

The increased security only affects the manual entry of PCM Codes in the Immobilizer Setup Tool. A PCM Code is the method of authentication for certain functions. For example, IMMOBI, ONE-PUSH START.

Thank you for your attention.

Special Tools Team
American Honda Motor Co., Inc.
1919 Torrance Blvd
Torrance, CA 90501-2746