



LETTRE DE SERVICE SERVICE LETTER

MODEL/YEAR MODÈLE /ANNÉE	DATE OF ISSUE DATE EN VIGUEUR	LETTER NUMBER NUMÉRO DE LA LETTRE
<i>All Acura models</i>	NOV. 23, 2018	J-10-18

STRUCTURAL ADHESIVE FOR BODY COMPONENT REPLACEMENT

Body component replacement procedures for some models require the use of a 2-part epoxy adhesive, L&L Products L-0504.

This adhesive is no longer available. Instead, use 3M Impact Resistant Structural Adhesive 07333 as an alternative. This adhesive is commercially available from local body parts distributors.

